



CABLE HARNESS REPAIR KIT

FOR BLOWER CONTROLLER V42-79-0004 | 6441.L2

23901

The cable harness and its plugs must be inspected for damage when exchanging the blower controller. If this is damaged then this must also be exchanged. A defective cable harness would damage the new controller. Ensure that the plugs are properly engaged and tight after exchanging.


DEFEKTIVE PLUG ON THE CABLE HARNESS



Regulator, passenger
compartment fan
V42-79-0004
6441.L2



CABLE HARNESS REPAIR KIT



Citroën	C2, C3, C5
Nissan	Micra, Note
Renault	Clio, Megane, Modus, Scénic, Twingo
Peugeot	207, 406, 607, 1007
suitable for	V42-79-0004 6441.L2

X-Ref 4046001798115

V42-83-0003

Notes: Temporary offers are only valid while stocks last. All offers remain subject to prior sale. Our general terms and conditions of sale and delivery as well as our warranty conditions apply, which are available for download on our website. All prices are net prices. Errors excepted. Reference numbers of vehicle manufacturers are non-binding and no indication of origin. They may not be disclosed in invoices. © VIEROL AG