

SENSOR, CRANKSHAFT PULSE

11604



SYMPOMS

- Engine control unit operates in the emergency operation, at worst engine stall
- Engine control symbol lights up
- An error code is saved
- Increased fuel consumption



CAUSES OF FAILURE

- Breakage or mechanical damage to the encoder wheel
- Contacting problems
- Temperature problems
- Internal short circuits
- Line short circuits



ATTENTION

- The permissible tightening torque is max. 10Nm.
- The sensor is mounted by pushing it in (no slamming).
- There must be no forces acting on the plug or the ribs when using mechanical mounting aids.

SENSOR, CRANKSHAFT PULSE



BMW

E81, E82, E87, E88 (116 i – 120 i)
E90, E91, E92, E93 (316 i – 320 i)
E60, E61 (520 i)

X-Ref 13 62 7 594 047

13 62 7 548 660

V20-72-0542

Hinweise: Zeitlich befristete Angebote gelten nur, solange der Vorrat reicht. Zwischenverkauf vorbehalten. Es gelten unsere Allgemeinen Verkaufs- und Lieferungs- sowie Garantiebedingungen, die auf unserer Website zum Download bereitstehen. Alle Preise sind Nettopreise, zzgl. Mwst. Irrtum vorbehalten. Referenznummern der Fahrzeughersteller sind unverbindlich und keine Herkunftsbezeichnung. Sie dürfen in Rechnungen nicht weitergegeben werden. © VIEROL AG