

WHEEL HUBS & WHEEL BEARING KITS

SUITABLE FOR AUDI-VW AND BMW

WHEEL SUSPENSION | 18502 | 18503

- ✓ **Safety:** Preliminary product testing and lifetime test
- ✓ **Quick mounting:** supplies are included
- ✓ **Program:** comprehensive, competitive, up-to-date



FAILURE CAUSES

- Corrosion
- Cracks in the bearing
- Defective pulse generator
- Damage caused by hard shocks



| | |
|----------------------------|---|
| AUDI | A3, Q3, TT |
| VW | Beetle, Tiguan, Touran |
| Info | wheel hub rear axle, both sided, with integrated ABS ring |
| X-Ref 1T0 598 611 B | V10-6335 |



| | |
|----------------------------|---|
| AUDI | A3, TT |
| VW | Golf IV, New Beetle |
| Info | wheel hub front axle, both sided, with ABS ring |
| X-Ref 1J0 407 613 G | V10-1485 |



| | |
|----------------------------|---|
| AUDI | A1, A2 |
| VW | Fox, Polo |
| Info | wheel bearing kit front axle, both sided, for vehicles with ABS |
| X-Ref 6R0 407 621 A | V10-8259 |



| | |
|------------------------------|----------------------------------|
| BMW | E36, E46, E85, E86 |
| Info | wheel hub front axle, both sided |
| X-Ref 31 22 6 757 024 | V20-0517 |

Notes: Temporary offers are only valid while stocks last. All offers remain subject to prior sale. Our general terms and conditions of sale and delivery as well as our warranty conditions apply, which are available for download on our website. All prices are net prices. Errors excepted. Reference numbers of vehicle manufacturers are non-binding and no indication of origin. They may not be disclosed in invoices. © VIEROL AG